

# Pickwick Mill Dam Project

## Photos 4B & 4C Referenced on Photo Key

Photo 4B



Existing catwalk mount on the westerly side of Gate 1. View facing westerly.

Photo taken 06-10-2025

Photo 4C



Existing catwalk mount on the westerly side of Gate 2. View facing southerly.

Photo taken 06-10-2025

# Pickwick Mill Dam Project

## Photos 4D & 4E Referenced on Photo Key

Photo 4D



Existing catwalk mount on the westerly side of Gate 3. View facing Northwesterly.

Photo taken 07-08-2025

Photo 4E



Existing catwalk mount on the easterly side of Gate 3. View facing Southeasterly.

Photo taken 06-10-2025

# Pickwick Mill Dam Project

## Photos 5A Referenced on Photo Key



### Photo 5A

Steel dam gates and  
superstructure view from  
southwest facing northeast

Photo taken 07-08-2025

# Pickwick Mill Dam Project

## Photos 5B, 5C, & 5D Referenced on Photo Key

Photo 5B



Downstream side of the left (west) Gate 1.  
View facing southerly.

Photo taken 06-10-2025

Photo 5C



Downstream side of the (center) Gate 2.  
View facing southerly.

Photo taken 06-10-2025

Photo 5D



Downstream side of the right (east) Gate 3.  
View facing southerly.

Photo taken 06-10-2025

# Pickwick Mill Dam Project

## Photo 6 Referenced on Photo Key



### Photo 6

Area lying northerly of concrete spillway. Area to be supplemented with riprap. View facing southerly from middle of creek

Photo taken 07-10-2025