



A-15: NORTHWEST CORNER IN ENTRY CLOSET



A-16: VIEW OF AREA OF DISCOLORATION ON WALL AT CORNER



A-27: BASE OF FURNACE VENT, AGED AND DAMAGED METAL



A-28: UPPER CORNER OF FURNACE VENT AND EXISTING FLASHING



A-37: VIEW OF FLASHING ALONG EAST SIDE OF CHIMMNEY



A-38: OLDER DAMAGED FLASHING ALONG SIDE OF CHIMNEY



A-39: SOUTH SIDE OF CHIMNEY AT ROOF



A-40: GAP AT INTERSECTING FLASHING PIECES AT SOUTHEAST CORNER



A-43: SOUTHWEST CORNER, GAP BETWEEN CAP AND BRICK



A-44: VIEW OF TRANSITION AT ROOF FIELDS BETWEEN UNITS



A-61: GAPS AT INTERSECTING JOINTS IN TRIM BOARDS, NORTHWEST CORNER



A-62: VIEW OF GAPS AND SHRINKAGE OF TRIM BOARDS