


CAPITOL OFFICE BUILDING

MINNESOTA HOUSE OF REPRESENTATIVES RULES AND LEGISLATIVE ADMINISTRATION COMMITTEE






BASEMENT FLOOR



GROUND FLOOR



FIRST FLOOR



SECOND FLOOR (FLEX SPACE)



04 April 2014

SECOND FLOOR



04 April 2014

THIRD FLOOR (FLEX SPACE)



04 April 2014


LEVEL 3A

THIRD FLOOR



04 April 2014 CAPITOL OFFICE BUILDING | 10

MECHANICAL ROOF LEVEL



KEY CHANGES FROM ORIGINAL CONCEPTS: EXTERIOR MODIFICATIONS





SOUTH ELEVATION - REVISED (44% OPACITY)

- Elimination of exterior sun shade and columns
- Elimination of reflecting pool
- 3. Mechanical moved to rooftop creating interior space for 67 Senators
- 4. Reduction in conference room quantity and office size - creating interior space for 67 Senators
- 5. Simplification of the North facade less articulation Less glass on the South facade - more opacity
- 6. Reduction in the number of landscape trees
- Reduction in the landscape paver scope
- Elimination of the service tunnel at parking level
- Elimination of the 'blade' at roof level
- 10. Elimination of skylight options at roof level and green roof
- 11. Simplification of interior material palette
- 12. Potential elimination of exterior stair and or elevator



