


Climate impacts already here: Increased frequency and severity of flooding which destroy habitat



Garvin Brook (Winona County)



Severe floods leave vertical eroding banks, wide, shallow channels with cobble debris and no trout habitat

Garvin Brook
(Winona County)




Garvin restored to single, stable channel with depth and overhead trout cover

Garvin Brook





Flood filled channel



Little Stewart
flows under rubble

Restored channel at same location



Little Stewart



Severe flooding caused slope failures on Carlton County

Blackhoof River





Blackhoof River





Blackhoof River





Forest pests killing riparian forests in NE

