


SLR Area



- Sturgeon Lake Rd Phase 1: Overpass and connector stubs
- Sturgeon Lake Rd: deteriorated road adjacent to Phase 1 - Phase 2 base project of street and trail reconstruction with eco passages and railings

1:22,002





Raveling, Patching, Longitudinal and Transverse Cracking, Vinyl Fencing and Guardrail



Raveling, Potholes, Longitudinal and Transverse Cracking, Alligator Cracking, Vinyl Fencing and Guardrail



Raveling, Patching, Longitudinal and Transverse Cracking, Vinyl Fencing and Guardrail



Raveling, Potholes, Patching,
Longitudinal and Transverse Cracking



